

BUILDING SAFETY CERTIFICATE

No. _____

Dated: 05/06/2026

It is certified that the existing building Austin Public School
(name of the building or premises) at Bera Pokhara PO- Manpur West Tehsil- Haldwani Distt- Nainital
Uttarakhand 263239

(address) is having block(s)/Floor(s) as per details below:

Details of Block (s) in School	Block (1)	Block (2)	Block (3)	Block (4)	Block (5)	Block (6)
No. of Floors in Block	Ground floor	1 Floor				

The building is owned/occupied by Austin Public School
(name of the Institution) have complied with the Building safety requirements in accordance with National Building Code Rules, and verified by the officers concerned of PWD (Name of Department/Govt.) on 05/06/26 (date of inspection) in the presence of Dharmendra Singh Mehta, Karayal Chatur Singh PO- Manpur West Haldwani Nainital. (name and addresses of the Manager/Secretary or his representative) and that the building/premises is fit for occupancy for running school with effect from 05/06/25 for a period of 10 years in accordance with rule and subject to compliance of the specific conditions as appended.

1. Road at East
2. Mohan Chandra Tewari Land At West
3. Road At North
4. Land of Umesh Fartyal & Form House of Sharma Ji

Issued on 05/06/2026

* Strike out whichever is not applicable. In case of block is more than six use separate sheet for detail.

at HALDWANI

05/06/26
Assistant Engineer

Construction Division, P.W.D.

Signature with Seal: HALDWANI.

Name: Hemant Kumar Sah

Designation: Assistant Engineer

Name & Address of Department/ Office: P.W.D. Haldwani

Smelke
Manager

Austin Public School
Bera Pokra, Haldwani

(72)

Principal
Austin Public School
Bera Pokra, Haldwani